

# Optical Links for ATLAS Liquid Argon Calorimeter Front-end Electronics Readout

**Tiankuan (Andy) Liu**  
**on behalf of the ATLAS Liquid Argon Calorimeter Group**  
Department of Physics,  
Southern Methodist University,  
Dallas, Texas 75275, USA


TWEPP 2010 - Aachen, Germany  
September 22, 2010




# Outline

1. **ATLAS LAr optical links overview**
2. VCSEL problem and the possible fixes
3. Lessons learned in the optical links development
4. Summary

# ATLAS Liquid Argon Calorimeter (LAr)




- ~180,000 detector channels
- Front-end Electronics on the detector
  - 58 Front End Crates
  - 1524 Front End Boards (FEB)
  - 128 channels per FEB
- Back-end Electronics (150 meters away)
  - 16 Back End Crates
  - 192 Read Out Driver (ROD) Boards
- Fiber optical links between FE and BE
  - 1524 links, 1.6 Gbps per link
  - 1 fiber per FEB (128 channels)



Front End  
Crate




# ATLAS LAr optical links overview




- Developed by a collaboration of 5 institutions: CPPM, IPAS, ISN, KTH and SMU.
- Lasted for 6+ years: 1998 - 2004

- G-Link: commercial serializer/deserializer, specially ordered from Agilent, operating outside of specifications
- SMUX: an ASIC fabricated in DMILL, interface between G-Link TX and ADC data
- OTX, ORX: custom assembled optical interface modules, commercial VCSEL, PIN, laser driver, and TIA
- Components on front-end: radiation tolerant



# LAr optical links






# Outline

1. ATLAS LAr optical link overview
2. VCSEL problem and the possible fixes
  - Current Status
  - Failure analysis
  - Backup plans
3. Lessons learned in the optical link development
4. Summary

# VCSEL failure (S. Simion)

- The loss of one link means the loss of data of 128 channels. There are 1524 links in total.
- By now 24 dead OTXs are still inside the detector (+3 used for read back configuration of FEBs)
- Visually all OTX failures are either confirmed VCSEL failures when the parts were accessible and replaced or consistent with VCSEL failures (no light)





# Failure analysis



- A task force was created in December 2008 to deal with the VCSEL issue.
  - Plan A: replace the failed parts with similar devices IF the cause is understood and removed
  - Plan B: replace all parts with new production
- **Although a lot of attempts have been made to understand the failure cause,**
  - Humidity
  - Magnetic field
  - Electrostatic discharge (ESD)
  - Electrical overstress (EOS)
  - VCSEL fabrication defects
  - ...**so far we have not got to the root cause.**
- The VCSEL failures exist not only in ATLAS LAr, but also in other ATLAS detectors and LHCb.





# Optical Spectrum versus ESD

- In June 2009, from literature<sup>1</sup>, we realized that optical spectrum of a VCSEL becomes narrow after ESD damage. An experiment at SMU verified.



- We know ESD produces narrow optical spectrum, but we are not sure whether narrow optical spectrum is caused only by ESD


<sup>1</sup> T. Kim *et al*, *ETRI Journal*, Vol. 30(6), Dec 2008, pp.833-843



# Failure prediction (S. Simion)

- Is a VCSEL with narrow spectrum more likely to fail? The answer seems to be: yes.
- All optical spectra at the end of fibers have been measured three times (2009/7, 2009/10, 2010/2). Optical spectrum seems stable.


OTx width, serial number, failures and narrow spectra






Optical link died on July 13, 2010

We suspect it is not due to the VCSEL but other component in the FEB/OTX, but we cannot know for sure until we get the board out

OTx width optical spectrum stability



# Plan B: backup plans





It is worth mentioning that in order to exchange OTXs with either option, the biggest problem is to get the 1500 boards out of the pit, dismount cooling plates, solder OTX off the board....

		Plan B1	Plan B2
Developed by		LAL Orsay	SMU
New VCSEL		Optek	Finisar
VCSEL driver chip		same	Same
VCSEL driving circuitry		New	Same
<b>Redundancy</b>		<b>No</b>	<b>Yes</b>
<b>Compatibility</b>	Pin	Yes	Yes
	Front panel	Yes	Requires small modification of front panel
	fibers	Yes	Requires installing new(double) fibers
Status		Testing/qualification phase	tests including radiation qualification done





# Plan B2: a plan w/ redundancy

The present OTX:



present

The proposed dual-VCSEL OTX:




Plan B2





# Plan B2: production readiness

- 122 modules have been assembled at SMU
- Eye diagrams, average optical power, extinction ratio, rise/fall time, jitter, bit error rate (BER), and optical spectrum of all channels have been measured
- With 10 dB optical attenuation,  $BER < 10^{-12}$




Thank Cotty Kerridge, Chonghan Liu, Sophia Wang, Yuan Zhang for measuring the curves



# Radiation qualification of Plan B2

- 200 MeV proton beam
- All four modules continued to function throughout the test.
- The power supply current changed  $< 8\%$  with  $13.3 \text{ kGy}(\text{SiO}_2)$
- Cross section estimated  $< 1.8 \times 10^{-10} \text{ cm}^2$ . Correspondingly, **the estimated BER at ATLAS LAr is  $< 5 \times 10^{-14}$ ,  $\ll$  the industrial standard  $1 \times 10^{-12}$**





# Outline

1. ATLAS LAr optical link overview
2. VCSEL problem and the possible fixes
3. Lessons learned in the optical link development
4. Summary



# Lessons learned

- In the R&D phase
  - No system specification was studied in the beginning of R&D. In particular, no jitter requirement on the reference clock was realized until an issue occurred.
  - The importance of redundancy was not realized in the R&D. A dual channel redundancy scheme was developed in R&D, but declined in the final implementation due to the cost.
- In the integration phase
  - All components of optical links were soldered on front-end board or readout driver boards. The replacement of an OTX may damage a whole FEB. A pluggable module containing OTX or a mezzanine board containing an optical link will definitely help.
- In the production and quality assurance phase
  - We spent a lot of time to learn the OTX burn-in process.
  - We performed a reliability test on OTX, but the total device hours were too small to catch any VCSEL failure.





# Summary

- Other than the VCSEL failure at a few percent level, the optical link system for ATLAS LAr front-end electronics readout is functioning as designed and transmitting physics data.
- Although we have made many attempts to understand the cause of VCSEL failures, so far we failed to get to the root cause. However, optical spectrum seems effective at predicting which OTX is likely to fail.
- Two backup plans are under development and will be production ready before the next LHC shutdown.
- At some point, we have to make a decision among Plan A, B1 or B2:
  - Plan A : replace dead and narrow spectrum OTXs IF spectrum indication is still effective. We have enough good spares.
  - Plan B1 and B2: replace all OTXs with compatible design (B1) or redundant design (B2)
- The most profound lesson learned is that we cannot overemphasize the importance of redundancy in a system without much access.




# Backup slides

---



# VCSELs' reverse I-V curves


- An attempt conducted at SMU is to look for the ESD symptoms, the reverse leakage current and forward voltage threshold/slope.
- The I-V curves of functional VCSELs are different from the curves of dead VCSELs.
- **No indication of ESD damage is found in the spare OTXs.**





# VCSELS' forward I-V curves

- The I-V curves of functional VCSELS are different from the curves of dead VCSELS.
- No indication of ESD damage is found in the spare OTXs.



Thank Joseph Hashem and Chonghan Liu for measuring the curves




# Radiation qualification of Plan B2

- November 17-18, 2009 at Indiana University Cyclotron Facility (IUCF)
  - Conditions:
    - 4 modules, 8 channels
    - 198 MeV proton beam
    - Flux from  $4.86 \times 10^6$  to  $3.41 \times 10^9$  protons/cm<sup>2</sup>/s
    - Total ionization dose 7.51 kGy(SiO<sub>2</sub>)
    - Total fluence  $1.27 \times 10^{13}$  cm<sup>-2</sup>
  - Results:
    - **Comparing the pre-irradiation and post-irradiation parameters, we did not observe any radiation induced change in any channels**
    - The optical spectra pre-irradiation were not measured, so we cannot compare channel by channel pre- and post- spectral width. The post-irradiation spectral widths of all channels are within  $\mu \pm 3\sigma$  of the other twelve modules. All of the spectral widths of these four post-irradiation modules are higher than the average spectral width of the other twelve modules.
- June 7, 2010 at IUCF
  - Conditions:
    - 4 modules, 8 channels
    - 200 MeV proton beam
    - Flux from  $1.33 \times 10^7$  to  $1.39 \times 10^{10}$  protons/cm<sup>2</sup>/s
  - Results: next slide

# TID effects

- All four modules continued to function throughout the test.
- The power supply current changes  $< 8\%$





# Single event effects

Cross section estimated  $< 1.8 \times 10^{-10} \text{ cm}^2$ . Correspondingly, the estimated bit error rate at ATLAS LAr is  $< 5 \times 10^{-14}$ ,  $\ll$  the industrial standard  $1 \times 10^{-12}$ .

Module ID	Ch#	# of errors (bit)	fluence ( $\text{cm}^{-2}$ )	$\sigma$ ( $\text{cm}^2$ )	BER at ATLAS LAr
46	1	202	$7.06 \times 10^{12}$	$(28.6 \pm 2.0) \times 10^{-12}$	$(70.7 \pm 5.0) \times 10^{-17}$
	2	331		$(46.9 \pm 2.6) \times 10^{-12}$	$(115.8 \pm 6.4) \times 10^{-17}$
47	1	1284		$(181.9 \pm 5.1) \times 10^{-12}$	$(449.3 \pm 1.3) \times 10^{-16}$
	2	385		$(54.5 \pm 2.8) \times 10^{-12}$	$(134.7 \pm 6.9) \times 10^{-17}$
48	1	194	$2.26 \times 10^{14}$	$(85.8 \pm 6.2) \times 10^{-14}$	$(21.2 \pm 1.5) \times 10^{-18}$
	2	351		$(155.3 \pm 8.3) \times 10^{-14}$	$(38.4 \pm 2.0) \times 10^{-18}$
49	1	164		$(72.6 \pm 5.7) \times 10^{-14}$	$(17.9 \pm 1.4) \times 10^{-18}$
	2	259		$(114.6 \pm 7.1) \times 10^{-14}$	$(28.3 \pm 2.8) \times 10^{-18}$