

fast tuner parameters

type

- blade
- slide jack
- eccentric (symmetric/asymmetric) or lever-arm

actuators

- piezo / magnetostrictive
- number of actuators (1/2)
- arrangement if 2 actuators
- preload scheme

tuning ranges